



Work Order

View:

Work Order **045822**

Created By [REDACTED]

Date Created **Apr 12, 2011 11:19 AM**

Status **CLOSED**

Project

Description FG WOULD LIKE POOL SERVICED HE SAID SERVICE LIGHT IS ON , THE POOL WILL NOT HEAT UP TO THE TEMP, IT HAS BEEN ASKE DTO HEAT UP TO. THE NOTH SIDE HEATER DOES NOT SEEM TO BE WORKING... ROOM:POOL

Desired Date

Budget **\$0.00**

Organization

Organization **FACILITIES MGMT.**

FACILITIES MGMT.

Requestor **CR**

CUSTOMER REQUEST

Contact **LIZ.WOOD@GOV.OK.GOV**

Contact Phone **568-1292**

Contact Email **liz.wood@gov.ok.gov**

Property

Region **OKLAHOMA**

OKLAHOMA COUNTY

Facility **OKLAHOMA CITY**

OKLAHOMA CITY*

Property **GOV-MANSION**

GOVERNOR'S MANSION /

Classification

Problem Code

Type **MAINTENANCE**

MAINTENANCE

Category **CORRECTIVE**

FAILURE REPAIRS

Phase

Phase	Description	Location	Shop	Work Code	Priority	Status
001	FG WOULD LIKE POOL SERVICED HE SAID SERVICE LIGHT IS ON , THE POOL WILL NOT HEAT UP TO THE TEMP, IT HAS BEEN ASKE DTO HEAT UP TO. THE NOTH SIDE HEATER DOES NOT		CENTRAL MAINTENANCE	GENERAL	ROUTINE	CLOSED

Notes Log

Phase	001	Created By	KISEN HOUR	Add to Main Workdesk	No <input type="checkbox"/>
		Date Created	Apr 12, 2011 11:19 AM	Add to Module Workdesk	No <input type="checkbox"/>
Description	FG WOULD LIKE POOL SERVICED HE SAID SERVICE LIGHT IS ON , THE POOL WILL NOT HEAT UP TO THE TEMP, IT HAS BEEN ASKE DTO HEAT UP TO. THE NOTH SIDE HEATER DOES NOT SEEM TO BE WORKING... ROOM:POOL			Note Type	<input type="text"/>
				Channel Title	<input type="text"/>

Page of 1 Results 1 - 2 of 2

Notes Log

From contains

To

Edit Date	Editor	Name	Note Type	Notes
Apr 14, 2011 06:47 AM	RWHITE	<input type="text"/>		I SPOKE WITH LIZ ON THE BLINKING LIGHT AND EXPLAINED THAT THIS IS NOT A SERVICE LIGHT IT IS A REMOTE COM ERROR THAT IS IN THE FACTORY PROGRAMING. BOTH HEATERS WERE OPERATING WHEN CHECKED.
Apr 12, 2011 04:58 PM	RWHITE	<input type="text"/>		POOL IS AT 92-94 DEGREES ON POOL AND SPA.