-				-
-,	Δ	v.	N	л
Marie Marie	_	и	ı١	п

Hello, Logout _____

About Help

Work Order

Work Order

O41543

Created By
Date Created Jan 28, 2011 02:26 PM

THE HOT TUB IS TEMP IS SET TOO LOW... HAVE BEEN ASKED IF IT COULD GO HIGHER...
ROOM:POOL /HOT TUB

Desired Date
Budget

\$0.00

View: Select

Organization		Property		Classification	1
Organization	FACILITIES MGMT.	Region	OKLAHOMA	Problem Code	Ĺ
	FACILITIES MGMT.		OKLAHOMA COUNTY		
Requestor	CR	Facility	OKLAHOMA CITY	Туре	MAINTENANCE
	CUSTOMER REQUEST	D. 1049914 COS	OKLAHOMA CITY*	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	MAINTENANCE
Contact	LIZ WOOD	80.5	Onder tomes of the	25 500 77 77 70 20 70	
Contact Phone	521-9211	Property	GOV-MANSION	Category	CORRECTIVE
Contact Email	liz.wood@gov.ok.gov		GOVERNOR'S MANSION /		FAILURE REPAIRS

Phase

Phase	Description	Location	Shop	Work Code	Priority	Status
001	THE HOT TUB IS TEMP IS SET TOO LOW HAVE BEEN ASKED IF IT COULD GO HIGHER ROOM:POOL /HOT TUB		CENTRAL MAINTENANCE	GENERAL	ROUTINE	CLOSED

Z/AiM		Hello, Logout	_		About Help
Notes Lo	g				
Phase	001	Created Date C	-	Add to Main Workdesk	No No
	Description THE HOT TUB IS TEMP IS SET TOO LOW HAVE BEEN ASKED IF IT COULD GO HIGHER ROOM:POOL /HOT TUB			Workdesk Note Type Channel Title	
Page 1	of 1				Results 1 - 1 of 1
Notes Log From To				contains	
Edit Date	Editor	Name	Note Typ	e Notes	
Jan 28, 2011 04:24 PM	RWHITE			TURNE	ED HOT TUB UP TO 102 DEGREES.

(c) 2011 AssetWorks