



Work Order

View:

Work Order	048815	Created By		Status	<u>CLOSED</u>
		Date Created	May 27, 2011 02:11 PM	Project	
Description	GOVENOR WOULD LIKE THE POOL TO BE WORKING FOR THIS WEEK-END... IT HAS NOT BEEN HOT ENOUGH FOR HER TO GET IN... SHE SAID THE SPA IS NOT THE CORRECT TEMP AMD IF IT SAYS `104. THEN IT IS WRONG...PLESAE GET FIXED SO FAMILY CAN USE THIS WEEK-END ROOM:POOL			Desired Date	
				Budget	\$0.00
Organization		Property		Classification	
Organization	FACILITIES MGMT.	Region	OKLAHOMA	Problem Code	<u>GENERAL MAINT.</u>
	FACILITIES MGMT.		OKLAHOMA COUNTY		GENERAL MAINTENANCE,
Requestor	CR	Facility	OKLAHOMA CITY	Type	<u>MAINTENANCE</u>
	CUSTOMER REQUEST		OKLAHOMA CITY*		MAINTENANCE
Contact	LIZ WOOD	Property	GOV-MANSION	Category	<u>CORRECTIVE</u>
Contact Phone	568-1292		GOVERNOR'S MANSION /		FAILURE REPAIRS
Contact Email	liz.wood@gov.ok.gov				

Phase

Phase	Description	Location	Shop	Work Code	Priority	Status
001	GOVENOR WOULD LIKE THE POOL TO BE WORKING FOR THIS WEEK-END... IT HAS NOT BEEN HOT ENOUGH FOR HER TO GET IN... SHE SAID THE SPA IS NOT THE CORRECT TEMP AMD		CENTRAL MAINTENANCE	GENERAL	ROUTINE	CLOSED

Notes Log

Phase **001**

Created By

Date Created **May 27, 2011
02:11 PM**Add to Main Workdesk No Add to Module Workdesk No Note Type Channel Title

Description GOVENOR WOULD LIKE THE POOL TO BE WORKING FOR THIS WEEK-END... IT HAS NOT BEEN HOT ENOUGH FOR HER TO GET IN... SHE SAID THE SPA IS NOT THE CORRECT TEMP AMD IF IT SAYS `104. THEN IT IS WRONG...PLESAE GET FIXED SO FAMILY CAN USE THIS WEEK-END ROOM:POOL

Page of 1

Results 1 - 1 of 1

Notes Log

From contains To

Edit Date	Editor	Name	Note Type	Notes
May 27, 2011 04:11 PM	RDENNIS			TEAM 3 AND MYSELF CHECKED OUT THE SPA AND THE POOL TO MAKE SURE EVERYTHING WAS OPERATIONAL WE CHANGED THE FILTERS ON THE POOL AND MADE SURE THAT ALL FUNCTIONS WORKED PROPERLY I BRIEFED LIZ ON THE REMOTE CONTROL AND ITS USE FOR THE SPA. WE HAD TO RESET THE DREAKERS TO GAIN COMMUNICATION BACK TO THE REMOTE AND TURNED THE SPA ON. AGAIN IF THERE IS NO FLOW THEN THE HEATERS AND PUMPS WILL SHUT OFF THEREFORE CAUSING THE POOL AND SPA TO COOL.